

INSPECTION REPORT

Name of Work : CONSTRUCTION OF RCC DRAIN
IN 6TH CROSS ROAD AT
PRASHANTHA NAGARA IN WARD
NO 13, SHETTIHALLI SUB-
DIVISION

Work Order : EE/DD/WO/01/2016-17 Date 01.04.2016

Agency : M S MURULIDHARA

B.R No & Date : B.R.No:335/2016-17, Date: 30-07-2016

Bill Amount : Rs.8,05,006/-

Job Code : 013-16-000006


P.Code : P1771

Date of Inspection : 20-03-2017

The above said work "construction of RCC drain in 6th Cross Road at Prashantha nagara in Ward no 13, Shettihalli Sub div." was shown to me by the concerned ward Engineer.

The above said work is inspected by me along with the concerned Ward Engineer.

The work above is satisfactory.


MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ವಿಸ್ತ.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.




MANJUNATH. K
DGM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT